

**AUGUST 2016 OUTAGE SUMMARY**

Date	Duration (Min)	Number of Customers Affected	RUS Cause Code	Cause of Service Interruption (RUS Designation 1730A-119)	Substation	OH/ URD	Customer Minutes of Interruption
08/03/16	60	1	unknown	Fuse blown at take off	Absarokee	OH	60
08/03/16	60	18	300	Faulted URD primary	Columbus	URD	1080
08/04/16	110	1	unknown	Re-fused tap	Absarokee	URD	110
08/06/16	40	10	090	Lightning blew fuse at take off	Red Lodge	OH	400
08/08/16	80	4	690	Re-fused tap	Nye	OH	320
08/09/16	195	16	090	Thunderstorm/wind OCR opened	Roberts	OH	3120
08/11/16	30	1	110	BEC maintenance	Roberts	OH	30
08/12/16	40	12	690	Fuse open	Columbus	OH	480
08/16/16	60	26	110	Planned outage to change pole	Red Lodge	OH	1560
08/18/16	60	341	000	Northwestern Energy	Luther	OH	20460
08/19/16	55	130	090	Line outage	Edg/From	OH	7150
08/19/16	100	17	300	Bad lightning arrestor	Edg/From	OH	1700
08/19/16	150	34	690	Bird caused pole to catch fire	Belfry	OH	5100
08/20/16	75	2	690	Fuse open	Absarokee	OH	150
08/22/16	30	18	110	Planned outage to install new service	Roberts	URD	540
08/22/16	55	1	300	Changed out bad turtle	Roberts	OH	55
08/24/16	90	3	300	Faulted cable	Absarokee	URD	270
08/25/16	90	1	690	C phase out	Belfry	OH	90
08/28/16	50	10	690	Re-fused line	Luther	OH	500
08/29/16	60	12	690	Cattle rubbing Guy wire slapping conductors together	Columbus	OH	720
<b>TOTALS</b>	<b>1490</b>	<b>658</b>					<b>43895</b>

RUS CAUSE CODE KEY			
090	Weather	<b>Absarokee</b>	<b>4</b>
110	Planned Outage/Maintenance	<b>Belfry</b>	<b>2</b>
300	Other Material/Equipment Fault	<b>Columbus</b>	<b>3</b>
490	Trees	<b>E Rosebud</b>	<b>0</b>
500	Transformer	<b>Edg/From</b>	<b>2</b>
690	Animals	<b>Luther</b>	<b>2</b>
790	Public Caused	<b>Nye</b>	<b>1</b>
Other	Other	<b>Red Lodge</b>	<b>2</b>
		<b>Reed Pnt</b>	<b>0</b>
		<b>Roberts</b>	<b>4</b>